



Of Las Cruces

724 W. Palms Las Cruces, NM 88001

July 24, 2018

Microbial Growth Inspection completed on 07/24/2018 at 907 Pope St. Silver City, NM 88061

Upon inspection of the commercial building, it was discovered that there have been numerous roof leaks throughout several years, prior to new roof application. At the time of inspection there were areas of the original ceiling that manifested server staining from water and discoloration from soil and minerals washing in the affected locations.

One exception was discovered to have visible microbial growth located at the front rear corner of the building. The microbial growth present was approximately 4 inches by 4 inches in 2 areas. There is a possibility that more microbial growth could be present in that area in the wood joists and/or rim joists that is not currently visible.

Please note that SERVPRO Of Las Cruces and Kim Briggs, Microbial Growth Inspector, are not responsible for any future discovery of microbial growth present in this building and will not warranty against any such claims. SERVPRO Of Las Cruces and/or Microbial Growth Inspector are not Environmental Hygienists. SERVPRO Of Las Cruces and Kim Briggs are members of MICRO (Mold Inspection Consulting and Remediation Organization).

This report is an opinion based on experience. For more detailed and accurate information, test samples and laboratory determinations are recommended. No other services completed except the visual inspection.

Thank you,



Kim Briggs, Microbial Growth Inspector